```
COLORTRAC                                          MAR  2020
Release Notes
**********************************************************************
*                    SmartWorks TOUCH v1.40                          *
**********************************************************************
          For SmartLF SC Xpress and SmartLF SG scanners


Features added:
* None

Changes:
* None

Fixes:
* Added compatibility for SG36E


COLORTRAC                                          MAY   2018
Release Notes
**********************************************************************
*                    SmartWorks TOUCH v1.30                          *
**********************************************************************
          For SmartLF SC Xpress, SmartLF SG and GX+ T56 scanners


Features added:
* None

Changes:
* None

Fixes:
* Foreground and Background setting issue
* SG black scan in colour mode issue
* Unwanted page error issue when using multipage PDF or TIFF


COLORTRAC                                          MARCH 2018
Release Notes
**********************************************************************
*                    SmartWorks TOUCH v1.20                          *
**********************************************************************
          For SmartLF SC Xpress, SmartLF SG and GX+ T56 scanners

THIS V1.2 RELEASE REQUIRES A MANUAL UNINSTALL OF ANY PREVIOUS VERSION

A change of installer means that for this version only the uninstall
of any previous SmartWorks TOUCH program cannot be automated. It must
be manually removed. See below for instructions.

IMPORTANT:To uninstall any previous SmartWorks TOUCH program go to the
Windows Control Panel, Programs and Features and locate SmartWorks TOUCH
then click Uninstall. This version can be installed directly from the
web page or saved to disk first. To install from the self-extracting file
download to a temporary folder and double-click the file. Follow the
on-screen prompts. Administration privileges are recommended.

INTERNET CONNECTION DURING INSTALLATION

This release of the Smartworks TOUCH installer checks to see if the
Microsoft libraries required by the program are installed on the host
computer. If the libraries are not present the installer will download
them from the internet and install them automatically.


Features added:
* Support for SmartLF SG added. IMPORTANT. This software only supports
a USB connection to the SG scanner.

Changes:
* None

Fixes:
```

* Adaptive thresholding no longer shortens scan in paper direction during
save for some settings.

COLORTRAC   DECEMBER 2015
Release Notes
****
*   SmartWorks TOUCH v1.15   *
****
         For SmartLF SC Xpress and GX+ T56 scanners

IMPORTANT: INTERNET CONNECTION REQUIRED

This release of Smartworks TOUCH and SmartWorks TOUCH MFP installer checks
to see if the Microsoft libraries required by the program are installed on
the host computer. If the libraries are not present the installer will
download them from the internet and install them automatically.

Features added:
* Bulgarian language support

Changes:
* None

Fixes:
* Scaling issues when printing and copying through Windows to HP T520 and
other HP printers sharing the same engine.
* Erratic crop box movement problem corrected for larger scan files

Known issues:

* File pathnames on certain networks may not be stored or open properly
  again after a program restart.
* Unplugging USB memory during write crashes program

COLORTRAC   NOVEMBER 2015
Release Notes
****
*   SmartWorks TOUCH v1.14   *
****
         For SmartLF SC Xpress and GX+ T56 scanners

IMPORTANT: INTERNET CONNECTION REQUIRED

This release of Smartworks TOUCH and SmartWorks TOUCH MFP installer checks
to see if the Microsoft libraries required by the program are installed on
the host computer. If the libraries are not present the installer will
download them from the internet and install them automatically.

Features added:
* None

Changes:
* Print-side sRGB colour adjusted to remove slight yellow coloration from
Windows printer driver output during copy and print (not evident in scans).

Fixes:
* Erratic crop box movement problem corrected for larger scan files

Known issues:

* File pathnames on certain networks may not be stored or open properly
  again after a program restart.
* Unplugging USB memory during write crashes program

```
COLORTRAC                                      SEPTEMBER 2015
Release Notes
************************************************************************
*                    SmartWorks TOUCH v1.12                           *
************************************************************************
          For SmartLF SC Xpress and GX+ T56 scanners


IMPORTANT: INTERNET CONNECTION REQUIRED

This release of Smartworks TOUCH and SmartWorks TOUCH MFP installer checks
to see if the Microsoft libraries required by the program are installed on
the host computer. If the libraries are not present the installer will
download them from the internet and install them automatically.

Features added:
* None

Changes:
* Automatic document size detection has been altered to allow correct detection
  of document width if placed anywhere in the middle of the scanner but covering
  the middle paper sensor. Automatic paper detection no longer works from the
  side of the scanner
* Improvements to connection awareness after scanner is woken from sleep condition

Fixes:
* Autosize effectiveness improved

Known issues:

* File pathnames on certain networks may not be stored or open properly
  again after a program restart.
* Unplugging USB memory during write crashes program




COLORTRAC                                          JUNE 2015
Release Notes
************************************************************************
*                    SmartWorks TOUCH v1.04c                          *
************************************************************************
          For SmartLF SC Xpress and GX+ T56 scanners

IMPORTANT: INTERNET CONNECTION REQUIRED

This release of Smartworks TOUCH and SmartWorks TOUCH MFP installer checks
to see if the Microsoft libraries required by the program are installed on
the host computer. If the libraries are not present the installer will
download them from the internet and install them automatically.

Features added in 1.04c:
* None

Fixes:
* Installer changes to automatically install localised Microsoft components
  if these are not already present on the host computer.

Known issues:
* Automatic size detection subtracts any positive origin displacement
  of the document from the overall document width.  When placed below the
  origin point document size detection fails
* File pathnames on certain networks may not be stored or open properly
  again after a program restart.
* Unplugging USB memory during write crashes program


COLORTRAC                                           MAY 2015
Release Notes
************************************************************************
*                    SmartWorks TOUCH v1.04a                          *
************************************************************************
          For SmartLF SC Xpress and GX+ T56 scanners
```

The Smartworks TOUCH and SmartWorks TOUCH MFP installation CD requires
the following Microsoft products to be preinstalled on the host computer.
These components are language dependant and are not included on the
installation CD to avoid installing unwanted material onto your computer.

Do not uninstall any Microsoft packs as more recent versions of these
packs do not always include the functionality of earlier releases.

Microsoft .NET Framework 4.5.2
Microsoft Visual C++ Redistributable(x86) for Visual Studio 2013
Microsoft Visual C++ Redistributable(x86) for Visual Studio 2012

If the above are not installed TOUCH will not open and the program
will attempt to display a warning message although this may not always
occur. If TOUCH does not open please do the following:

1. Uninstall SmartWorks TOUCH from the Windows Control Panel

2. Use Control Panel Installed Programs to check the .NET Framework release.
Older .NET Framework 4 should be updated to .NET Framework 4.5.1 or the latest
Framework 4.5.2. NET Framework 3.5 and earlier releases should not be removed.

3. Check installed programs for Microsoft Visual C++ Redistributable(x86)
for Visual Studio 2013. If you require DWF scan file format you will need
to install Microsoft Visual C++ Redistributable(x86) for Visual Studio 2012
as well. Visual Studio 2013 does not replace 2012 and both versions are
required for DWF.

4. Reboot the computer

5. Re-install SmartWorks TOUCH or SmartWorks TOUCH MFP from the installation CD.

The software should now open normally.

Features added in 1.04a:
None

Bug(s) fixed:
* Reduced Microsoft installation dependencies

Known issues:

* Program may fail to open and report missing .NET or Microsoft
  Visual C++ Re-Distributable Packages on certain computers - see
  instructions above.
* Program may fail to open without reporting missing .Microsoft
  components on certain computers - see instructions above.
* Unplugging USB memory during write crashes program

COLORTRAC   MARCH 2015
Release Notes
****
*   SmartWorks TOUCH v1.0   *
****
          For SmartLF SC Xpress and GX+ T56 scanners

Known issues:

* Unplugging USB memory during write crashes program