


Service Bulletin No 106: SmartLF SC Energy Star Firmware V2.02 Release



1. Colortrac products affected: Colortrac SmartLF SC Energy Star Scanners.

- SmartLF SC 25 Xpress / mfp serial numbers:
H2409995 onwards.
- SmartLF SC 36 Xpress / mfp serial numbers:
H2409025 onwards
Including: H2405372, H2405388, H2405399 – H2405401,
H2405435 – H2405441, H2405501 – H2405504,
H2405510, H2405519, H2406576, H2406579,
H2407617 – H2407688.
- SmartLF SC 42 Xpress / mfp serial numbers:
H2410070 onwards
Including: H2405445 – H2405454, H2407630 – H2407639,
H2407696 – H2407704, H2408829, H2408834,
H2408835, H2409882.

2. Issue: SmartLF SC Energy Star firmware v2.02 has been released for scanners fitted with the newer Energy Star compatible Main Boards only.

- Enhancements for improved image quality
- Scanner ejects loaded paper before entering sleep mode

3. Procedure: Download the firmware from:

<http://www.colortracsupport.com>.

4. Part Number: There is no part number for the SC Scanners firmware.

